

BIKE SERVICING & REPAIRS

WORKSHOP PRICELIST



GENERAL SERVICING

Accessories purchased from us fitted free of charge (except full-length mudguards).

We will undertake any other stand-alone repair charged at £15 per 15 minutes (£15 minimum).

WHEELS

- Puncture _____ **£5**
- Puncture - hub gear rear wheel _____ **£20**
- Full-length mudguard fitting _____ **£20**
- Wheel true _____ **£18**
(plus £1 labour charge for each spoke replaced)
- Hub service (per hub) _____ **£20**
- Wheel build (per wheel) _____ **£40**
(includes silver double butted spokes. Black & specialist spokes extra)

OTHER SERVICES

- Disc brake bleeding (each) _____ **£25**
- Headset fitted _____ **£25**
(includes frame preparation)
- Bottom bracket fitted _____ **£25**
(includes frame preparation)

BRONZE SERVICE **£35**

Excludes cost of parts.

- Frame & forks wiped down and checked for alignment
- Gears and brakes adjusted
- Chain checked and lubricated
- Wheels and tyres inspected for wear
- Full safety check

SILVER SERVICE **£60**

Recommended every 3 to 9 months, depending on use. Excludes cost of parts. **Bronze service** plus:

WHEELS

- Hubs and rims checked for damage and wear
- Bearings checked for free movement and adjusted (if applicable)
- Wheels trued and spokes tensioned

HEADSET

- Checked for free movement and adjusted as necessary

BOTTOM BRACKET

- Checked for free movement and adjusted as necessary

DRIVE TRAIN (chain, cassette and chainset)

- Removed, cleaned, checked for wear and re-lubricated

BOTTOM BRACKET

- Checked for effective operation and adjusted

GOLD SERVICE **£110**

Full strip down to frame and forks. Recommended every 12 to 18 months, depending on use. Excludes cost of parts. **Silver service** plus:

FRAME & FORKS

- Frame cleaned and checked for alignment and damage, threads cleaned and checked
- Frame and disc mounts faced (if applicable)

WHEELS

- Hubs disassembled, cleaned, inspected and reassembled

HEADSET

- Removed, cleaned, regreased (if applicable), refitted & checked for movement (replacement fitted if necessary)

BOTTOM BRACKET

- Removed, cleaned, regreased (if applicable), refitted & checked for movement (replacement fitted if necessary)

BROMPTON SERVICING **£175** (Only available in Brompton accredited stores)

Carried out by our Brompton-qualified mechanics. This is a specific Brompton service. Includes **Gold Service** plus:

- Rear hinge replacement
- Seat sleeve replacement
- New decals